

Submit 3 Copies to  
Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

**DISTRICT I**

P.O. Box 1980, Hobbs, NM

**DISTRICT II**

P.O. Drawer DD, Artesia, NM 88210

**DISTRICT III**

1000 Rio Brazos Rd., Aztec, NM

**OIL CONSERVATION DIVISION**

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-045-28219
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>	
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name State Gas Com AA	
8. Well No.	1
9. Pool name or Wildcat Basin Fruitland Coal Gas	
4. Well Location Unit Letter <u>K</u> : <u>1535</u> Feet From The <u>SOUTH</u> Line and <u>2275</u> Feet From The <u>WEST</u> Line Sectio <u>36</u> Township <u>30N</u> Rang <u>8W</u> NMPM <u>San Juan</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

**SUNDY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <u>Coal Seam</u>	
2. Name of Operator AMOCO PRODUCTION COMPANY Attention: <u>Mary Corley</u>	
P.O. Box 3092 Houston TX 77253	
3. Name of Operator AMOCO PRODUCTION COMPANY Attention: <u>Mary Corley</u>	
4. Well Location Unit Letter <u>K</u> : <u>1535</u> Feet From The <u>SOUTH</u> Line and <u>2275</u> Feet From The <u>WEST</u> Line Sectio <u>36</u> Township <u>30N</u> Rang <u>8W</u> NMPM <u>San Juan</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice Report or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☒ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: Cleanout, run liner & perf. ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed)

5/14/99 MIRUSU ND tree, rig up BOP's. RU wireline & set TBG plug @ 2750'. Blow TBG down. Held OK. Finish test all equipment. Unset hanger & TOH w/TBG. PU TIH w/6 1/4" bit 4 3/4" DCs, 3 1/2" DP & tag bridge @ 2788'. Circ w/air mist 1500 CFM & 12 BPH & C/O @ 2788'. Continue C/O to 2883' found no fish obstruction, circ rate 1500 CFM & 10 BPH mist. Fish fell into rat hole tight @ 2874'. C/O 4' tight hole to 2874'. TOH change rams & run 231' 5 1/2" liner set @ 2814' & top @ 2643'. RU & run GR CCL logs.

Perf Fruitland Coal Seam @ 2694' - 2705' w/4JSPF, .540 in diameter, total shots fired - 44. Perf 2nd stage @ 2722' - 2739' w/4JSPF, .540 in diameter, total shots fired - 68. Perf 3rd stage @ 2765' - 2822' w/4JSPF, .540 in diameter, total shots fired - 228. TIH W/TBG & land @ 2765'.

5/20/99 ND BOP NU WH. RDMOSU. Return well to production.

RECEIVED  
AUG 05 1999

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

*Mary Corley*

TITLE

Sr. Business Analyst

TYPE OR PRINT NAME

Mary Corley

TELEPHONE NO.

281-366-4491

(This space for State Use)

ORIGINAL SIGNED BY ERNIE BUSCH

DEPUTY OIL & GAS INSPECTOR, DIST. #

AUG 16 1999

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: