F. Lac Casing S Csg.Perf.	2160/S; 410/W Cu.ft. ———————————————————————————————————		Elev6	Elev. 6080 GL Spd		Comp			TD		РВ	
	@w <sup>-</sup>	Sx. Int	<b></b> @	w	Cu. ft. Sx. Pr Prod. Stim.	@	\	v	Cu. π. Sx. Τ		—@—	† Gas
P	BO/D MCF/D After	Hrs. SICP	PS	il After	Grav							A N S
TOPS		NITD	X	Well Log		TEST DAT						
Ojo Alamo		C-103	-	Plat	Х	Schd.	PC	Q	PW	PD	D	Ref.No.
Kirtland		C-104		Electric Log								
Fruitland				C-122								
Pictured Cliffs		Ditr	•	Dfa								
Chacra		Datr		Doc			·	1				1
Cliff House			·			İ		† — — — — — — — — — — — — — — — — — — —	<b>†</b>			
Menefee		1							<u> </u>	1		1
Point Lookout		1										1
Mancos		1						<b>†</b>		1		1
Gallup		1						İ		<del>                                     </del>		1
Greenhorn								<b> </b>	<u> </u>	<u> </u>		1
Dakota		1						† — —				1
Entrada		1						<u> </u>	1			1
		1		,	W/207.84 Acres							+

Florance Gas Com H #1 K-30-30N-09W

AMOCO PRODUCTION CO.



## United States Department of the Interior

BUREAU OF LAND MANAGEMENT Farmington Resource Area 1235 Laplata Highway Farmington, New Mexico 87401



IN REPLY REFER TO SF-078336-B et al. (WC) 3162.3-1 (019)

Amoco Production Company P.O. Box 800 Denver, CO 80201 OCT. 1 S 1991

Gentlemen:

Enclosed are your Applications for Permit to Drill well Nos:

- 1. 14 Barrett A, sec. 19, T. 31 N., R. 9 W., San Juan County, NM, lease SF-078336-B.
- √2. 64 Mudge B, sec. 20, T. 31 N., R. 11 W., San Juan County, NM, lease SF-078096.
- √ 3. 62 Mudge B, sec. 21, T. 31 N., R. 11 W., San Juan County, NM, lease SF-078096.
- $\sqrt{4}$ . 1 Florance Gas Com H, sec. 30, T. 30 N., R. 9 W., San Juan County, NM, lease SF-077833.
- 5. 11 Heaton A, sec. 28, T. 31 N., R. 11 W., San Juan County, NM, lease SF-078097.

As discussed with Cindy Burton of your company on, October 9, 1991, the subject APDs are rescinded and returned due to drilling not being commenced within the approved period of time.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

John L. Keller Chief, Branch of Mineral Resources

Enclosures

New Mexico Oil Conservation Division, 1000 Rio Brazos Rd., Aztec, NM 87410

ABANDONEL LOCATION

OCT 21 1991.

OIL CON. DIV.