



# United States Department of the Interior

BUREAU OF LAND MANAGEMENT  
FARMINGTON RESOURCE AREA  
1235 LAPLATA HIGHWAY  
FARMINGTON, NEW MEXICO 87401

TAKE  
PRIDE IN  
AMERICA

NM-10561 et. al. (WC)  
3162.3-1.0 (019)

CERTIFIED - RETURN RECEIPT REQUESTED  
P 253 046 160

DEC. 11 1990

Dugan Production Corporation  
P.O. Box 420  
Farmington, NM 87499

## ABANDONED LOCATION

Gentlemen:

Enclosed are your Applications for Permit to Drill (APD's) for the following wells:

1. No. 2 Atlantis, NW/4NE/4 sec. 3, T. 30 N., R. 14 W., San Juan County, New Mexico, lease NM-10561.
2. No. 3 Atlantis, SW/4NW/4 sec. 3, T. 30 N., R. 14 W., San Juan County, New Mexico, lease NM-10561.
3. No. 1 Pompey, NE/4NW/4 sec. 4, T. 30 N., R. 14 W., San Juan County, New Mexico, lease NM-12086.
4. No. 2 Pompey, NE/4NW/4 sec. 4, T. 30 N., R. 14 W., San Juan County, New Mexico, lease NM-12086.

As discussed with Jim Jacobs of your company on October 18, 1990, the subject APDs are rescinded and returned due to drilling not being commenced within one year of the approval date and within the second six month extension period.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office has not received comment within 30 days, it will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

/s/ John L. Keller

Ron Fellows,  
FOR Area Manager

cc: New Mexico Oil Conservation Division, 1000 Rio Brazos Road,  
Aztec, NM 87410

**RECEIVED**  
DEC 12 1990  
OIL CON. DIV  
DIST. 3

F

30-045-27092

9/26/88

F. loc. 790N;1850E Elev. 5641 GL Spd. \_\_\_\_\_ Comp. \_\_\_\_\_ TD \_\_\_\_\_ PB \_\_\_\_\_  
 Cu. ft. Cu. ft. Cu. ft.  
 Casing S. \_\_\_\_\_ @ \_\_\_\_\_ W \_\_\_\_\_ Sx. Int. \_\_\_\_\_ @ \_\_\_\_\_ W \_\_\_\_\_ Sx. Pr. \_\_\_\_\_ @ \_\_\_\_\_ W \_\_\_\_\_ Sx. T. \_\_\_\_\_ @ \_\_\_\_\_  
 Csg. Perf. \_\_\_\_\_ Prod. Stim. \_\_\_\_\_

T  
R  
A  
N  
S

BO/D \_\_\_\_\_ Grav. \_\_\_\_\_ 1st Del. Gas \_\_\_\_\_  
 MCF/D After \_\_\_\_\_ Hrs. SICP \_\_\_\_\_ PSI After \_\_\_\_\_ Days GOR \_\_\_\_\_ 1st Del. Oil \_\_\_\_\_

TOPS		NITD <input checked="" type="checkbox"/>	Well Log	TEST DATA						
			Plat <input checked="" type="checkbox"/>	Schd.	PC	Q	PW	PD	D	Ref.No.
Ojo Alamo		C-103	Electric Log							
Kirtland		C-104								
Fruitland			C-122							
Pictured Cliffs		Ditr	Dfa							
Chacra		Datr	Dac							
Cliff House										
Menefee										
Point Lockout										
Mancos										
Gallup										
Greenhorn										
Dakota										
Entrada										
		Acres <del>320</del>								

P  
o  
o

I BAS.DAK. Co. SJ S 3 T 30N R14W UB Oper.DUGAN PRODUCTION CORP Les. ATLANTIS

No. 2

ATLANTIS#2

B-03-30N-14W

DUGAN PRODUCTION CORP.