Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED		
Budger Bureau No.	1004-0135	
Expires: March	31, 1993	

	LAND MANAGEMENT	5. Lease Designation and Serial No.
SUNDRY NOTICES AND REPORTS ON WELLS		NM x012641
	or to deepen or reentry to a different reservoir.	6. If Indian, Allottee or Tribe Name
· ·	PERMIT - " for such proposals	
USE APPLICATION FOR	PERIVIT - TOT SUCH DIODOSAIS	7. If Unit or CA, Agreement Designation
SUBMIT	IN TRIPLICATE DEC - 1 1999	
1. Type of Well		Blanco
Oil X Gas Other		8. Well Name and No.
2. Name of Operator	চাছা, হ	Blanco #204R
Phillips Petroleum Company		9. API Well No.
 Address and Telephone No. 5525 Highway 64, NBU 3004, Farming 	ton, NM 87401 505-599-3454	30-045-28776 10. Field and Pool, or exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey De		10. Field and Foot, of exploratory Area
Unit M, 854' FSL & 1303' FWL		Basin Fruitland Coal
Section 26,T31N, R8W		11. County or Parish, State
		San Juan, NM
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT	T, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	N
Notice of Intent	Abandonment	Change of Plans
	Recompletion	New Construction
X Subsequent Report	Plugging Back	Non-Routine Fracturing
	Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
	X Other PC Pump	Dispose Water
		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
The progressive cavity pump (stator the new configuration are as follow PC Pump (Stator) top set	r and rotor) has been replaced again on the ws:	subject well. Details of
2-7/8" tubing set @ 3158' With "F" nipple set @ 313 124 7/8" rods and 1 rotor	7. 32'.	85 CELVER 50 CO 15 FH 1: 25

