MERRION

OIL & GAS

PANTHER No. 2 API #30-045-29574 Section 25, T30N, R13W San Juan County, New Mexico



SLOPE TESTS

	Depth	Hole Deviation
#1	317'	1/2°
#2	850'	3/4°
#3	1350'	1°

I, Steven S. Dunn, being first duly sworn, depose and state that the attached and foregoing depth and hole deviation figures are true and correct to the best of my information and belief.

Steven S. Dunn

Subscribed and sworn before me this 17th of August, 1998

State of New Mexico } ss

County of San Juan }

Esther J. Greyeyes Notary Public

My Commission Expires: August 7, 2002