Submit 3 Copies

APPROVED BY___

CONDITIONS OF APPROVAL, IF ANY:

Form C-103

| strict Office STRICT I | | | artment Revised 1-1-89 |
|--|--|--|--|
| | OIL CONSERVAT | | WELL API NO. |
| D. Box 1980, Hobbs NM 88241-1980 | 2040 Pacheco St. Santa Fe, NM 87505 | | 30-045-30272 |
| STRICT II; D. Drawer DD, Artesia, NM 88210 | Santa Fe, IN | IM 8/303 | 5. Indicate Type of Lease STATE FEE X |
| <u>STRICT III</u> 00 Rio Brazos Rd., Aztec, NM 87410 | | | 6. State Oil & Gas Lease No. |
| SUNDRY NO | TICES AND REPORTS ON | WELLS | |
| (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEFEND OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS) | | | 7. Lease Name or Unit Agreement Name Aztec Com 4 |
| Type of Well: | he . | NOV 2000 | 7.2000 00 |
| ÖIL GAS WELL X | OTHER | A STATE OF S | |
| Name of Operator | 1. | | 8. Well No. |
| oss Timbers Operating Com | pany | | #1 |
| | K. Ste 1 Farmington, NM 87401 | | 9. Pool name or Wildcat Basin Dakota / Blanco Mesaverde |
| Well Location Unit LetterF: 237 | 0 Feet From The North | Line and 204 | 45 Feet From The West Line |
| Section 16 | Township 30N | Range 11W | NMPM San Juan County |
| | 10. Elevation (Show wh | nether DF, RKB, RT, GR, etc | |
| | | 5691' Ground Level | |
| . Check A NOTICE OF IN | * * * | 1 | ice, Report, or Other Data SSEQUENT REPORT OF: |
| 707102 07 110 | | , | |
| RFORM REMEDIAL WORK | PLUG AND ABANDON | REMEDIAL WORK | ALTERING CASING |
| IPORARILY ABANDON | CHANGE PLANS | COMMENCE DRILLING | G OPNS. X PLUG AND ABANDONMENT |
| L OR ALTER CASING | | CASING TEST AND CE | EMENT JOB |
| 1ER: | | OTHER: | |
| Describe Proposed or Completed C work) SEE RULE 1103. | OperationsClearly state all pertinen | t details, and give pertinent | dates, including estimated date of starting any pro |
| Cross Timbers Operating | Co. spudded the above me | ntioned well on 10/3 | |
| jts of 8-5/8", 32.0#, J cement. 12 bbls (67 cu | | 5' KB. The casing w rculated to surface. | 11/00. Cross Timbers has also set 9 was cemented with 250 sx (286 cuft) of 12 hours after the cement job, the 1/1/00. |
| jts of 8-5/8", 32.0#, J cement. 12 bbls (67 cu BOP stack was installed | ft) of good cement was ci and pressure tested. Dr | 5' KB. The casing w rculated to surface. illing Resumed on 11 | vas cemented with 250 sx (286 cuft) of 12 hours after the cement job, the 1/1/00. |
| jts of 8-5/8", 32.0#, J cement. 12 bbls (67 cu BOP stack was installed | ft) of good cement was ci and pressure tested. Dr | 5' KB. The casing wrculated to surface. illing Resumed on 11 | vas cemented with 250 sx (286 cuft) of 12 hours after the cement job, the 1/1/00. |

TITLE _