



Key Energy Services, Inc.

Four Corners Division
5651 US Highway 64
P.O. Box 900
Farmington, NM 87499

Phone: 505-327-4935
Fax: 505-327-4962

May 9, 2001


Phillips Petroleum Company
5525 Hwy 64 NBU 3004
Farmington, NM 87401

Attn: Patsy Clugston

Rig no. 53

This letter is to certify that Key Energy Services, Inc., did run deviation surveys at the listed depths on the San Juan 32-8 26A well in S16-T31N-R08W, in San Juan county, New Mexico.

Depth	Deviation	Depth	Deviation
350'	$\frac{3}{4}^{\circ}$	3568'	$1\frac{1}{4}^{\circ}$
845'	$\frac{3}{4}^{\circ}$	4068'	3°
1372'	$1\frac{1}{4}^{\circ}$	4568'	$4\frac{3}{4}^{\circ}$
1867'	$\frac{3}{4}^{\circ}$	5064'	6°
2364'	$\frac{3}{4}^{\circ}$	5220'	6°
3052'	$\frac{3}{4}^{\circ}$	5378'	6°



To the best of my knowledge, I swear this information to be true.

Sincerely,

J.D. Griffith
Drilling contract manager

Notary Public
My commission expires: 6/26/02

