

DISTRICT I
1625 N. French Dr., Hobbs, NM 87240
DISTRICT II
811 South Frist, Artesia, NM 88210
DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410
DISTRICT IV
2040 South Pacheco, Santa Fe NM 87505

OIL CONSERVATION DIVISION

2040 S. Pacheco
Santa Fe, NM 87505

WELL API NO.	30-045-30304
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	NEW MEXICO COM C
8. Well No.	1-C
9. Pool Name or Wildcat	BLANCO MESA VERDE
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 5930' GR	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well:	OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator	Four Star Oil and Gas Co.
3. Address of Operator	3300 N. Butler Ave, Ste 100 Farmington NM 87401
4. Well Location	Unit Letter <u>C</u> : <u>1085</u> Feet From The <u>NORTH</u> Line and <u>2155</u> Feet From The <u>WEST</u> Line Section <u>36</u> Township <u>T30N</u> Range <u>R10W</u> NMPM <u>SAN JUAN</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 5930' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☒
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Four Star Oil and Gas Co. has completed the following in the subject well.

12/17/2000 Run 107 joints of 7" N-80, 23#, LT&C casing to 4,941'. Pump 441 sacks LITECRETE cement. Lost 100% returns after pumping 5 bbls into tail slurry. Bumped plug with 500 psi.

* Report cement T&P

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Arthur D. Archibeque TITLE Eng. Assistant

DATE 12/21/00

TYPE OR PRINT NAME Arthur D. Archibeque

Telephone No. 325-4397

(This space for State Use)

APPROVED BY Charles Thurman TITLE DEPUTY OIL & GAS INSPECTOR, DIST. 43

DATE DEC 26 2000

CONDITIONS OF APPROVAL, IF ANY:

*