

DISTRICT I  
1625 N. French Dr., Hobbs, NM 87240  
DISTRICT II  
811 South Frist, Artesia, NM 88210  
DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410  
DISTRICT IV  
2040 South Pacheco, Santa Fe NM 87505

**OIL CONSERVATION DIVISION**

2040 S. Pacheco  
Santa Fe, NM 87505

WELL API NO.	30-045-30306
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	SCHUMACHER
8. Well No.	1-B
9. Pool Name or Wildcat	BLANCO MESA VERDE
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	6219' GR

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS."

1. Type of Well:	OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator	FOUR STAR OIL AND GAS COMPANY
3. Address of Operator	3300 N. Butler Ave. Ste 100 Farmington NM 87401
4. Well Location	Unit Letter <u>F</u> : <u>1955</u> Feet From The <u>NORTH</u> Line and <u>1905</u> Feet From The <u>WEST</u> Line Section <u>18</u> Township <u>T30N</u> Range <u>R10W</u> NMPM <u>SAN JUAN</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	6219' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☒  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Four Star Oil and Gas Co has completed the following in the subject well.

11/14/00 Ran 129 joints 5-1/2", 15.5#, J-55, LT&C casing to 5,395'. Pumped 676 sacks LITECRETE cement, lost circulation after pumping 150 sacks of lead cement. Reduced pump rate to 2 BPM, did not re-establish circulation. Bumped plug with 1000psi.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Arthur D. Archibeque TITLE Eng. Assistant DATE 11/16/00  
TYPE OR PRINT NAME Arthur D. Archibeque Telephone No. 325-4397

(This space for State Use)  
ORIGINAL SIGNED BY CHARLIE T. PERMAN

APPROVED BY CHARLIE T. PERMAN TITLE STATE OIL & GAS INSPECTOR, DISTRICT IV DATE NOV 21 2000

CONDITIONS OF APPROVAL, IF ANY:

\*