



Key Energy Services, Inc.
Four Corners Division
P.O. Box 900
5651 US Highway 64
Farmington, NM 87499
Phone: 505-327-4935
Fax: 505-327-4962

December 11, 2000

Koch Exploration Company
P.O. Box 489
Aztec, NM 87410

This is to certify that Key Energy Services, Inc. did run deviation surveys at the listed depths on your Carle #2B well, in S10-T30N-R11W, in San Juan county, New Mexico.

H - 20

Depth	Deviation	Depth	Deviation
122'	$\frac{3}{4}^{\circ}$	1565'	$\frac{3}{4}^{\circ}$
242'	$\frac{3}{4}^{\circ}$	2062'	$1\frac{1}{4}^{\circ}$
750'	$\frac{1}{2}^{\circ}$	2502'	1°
1247'	$\frac{3}{4}^{\circ}$		

Drilled with air hammer from 2551' to 4900'

To the best of my knowledge, I swear this information to be true.

Sincerely,

J.D. Griffith

Drilling contract manager

Notary Public

My commission expires:

6/26/02