

Deviation Report

Name of Company Burlington Resources Oil & Gas Company	Address P.O. Box 4289, Farmington, NM 87499	
Lease Name and Number RIDILE #2C	Unit Letter -800 FSL -1955 FWL	Sec. Twn. Rge. 03-030N-009W
Pool and Formation Blanco PC/Blanco MV	County SAN JUAN	State NEW MEXICO

<u>Depth (ft)</u>	<u>Deviation (degrees)</u>
193	1.00
710	0.75
1 209	1.00
1 705	1.00
2 170	0.25
2 632	0.50
3 220	0.50
5 370	0.25

Air Hammer Used? ☒ YES ☐ NO

I, the undersigned, certify that I, acting in my capacity as Petroleum Engineer for Burlington Resources Oil & Gas Company, am authorized by said Company to make this report; and that this report was prepared under my supervision and directions, and that the facts stated herein are true to the best of my knowledge and belief.

Burman D. Shurt

Subscribed and sworn to before me this 12th day of June, 2001.

Timatha Winsatt

Notary Public in and for San Juan County, New Mexico

My Commission expires September 15, 2004.

LATTITUDE: 36°42.9'
LONGITUDE: 107°33.4'



Reserve Pit Dike: to be 8' above Deep side (overflow - 3' wide and 1' above shallow side).
Blow Pit: overflow pipe halfway between top and bottom and to extend over plastic liner and into blow pit.

[illegible]

B-B'							
6782'							
6772'							
6762'							

[illegible]

Note: Contractor should call One-Call for location of any marked or unmarked buried pipelines or cables on well pad and/or access road at least two (2) working days prior to construction