

TABULATION OF DEVIATION TESTS

CROSS TIMBERS OPERATING COMPANY

Depth	Degrees	Depth /	Detrees
500'	0°		879
1,000'	1°	,	
1,500'	1°		
2,378'	1°		

$\underline{\mathbf{A}} \ \underline{\mathbf{F}} \ \underline{\mathbf{F}} \ \underline{\mathbf{I}} \ \underline{\mathbf{D}} \ \underline{\mathbf{A}} \ \underline{\mathbf{V}} \ \underline{\mathbf{I}} \ \underline{\mathbf{T}}$

THIS IS TO CERTIFY that to the best of my knowledge the above survey details the deviation tests taken on CROSS TIMBERS OPERATING COMPANY'S

Pan Am Federal Gas Com "B" #3 in Section 31, T30N, R11W, API #30-045-30710 San Juan County, New Mexico.

	Signed	AN Pallon	\$17/01
	Printed Name	Jeffrey W. Patton	' /
	Title	Drilling Engineer	
THE STATE OF NEW MEXICO) COUNTY OF SAN JUAN BEFORE ME, the undersigned auth Patton, known to me to be Drilling I Company and to be the person whose who, being by me duly sworn on oat stated herein and that said statement SUBSCRIBED AND SWORN to be and State this 1711 day of	Engineer for <u>Cros</u> se name is subscri h, states that he h t is true and corr	s Timbers Operating bed to the above statem as knowledge of the facect.	nent, ets County
Notary Public	,	i/	
My Commission Expires: S:\Forms\Deviation Tests	-2004		