

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: September 30, 1990

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill, deepen or reentry to a different reservoir.

Use 'APPLICATION FOR PERMIT' for such proposals.

SUBMIT IN TRIPLICATE

1. Type of Well: oil well gas well **X** other
2. Name of Operator: **Devon Energy Corporation**
3. Address of Operator: **3300 N. Butler Avenue, Suite 211, Farmington, NM 87401**
4. Location of Well: (Footage, Sec., T., R., M., or Survey Description)

1777' FNL, 1375' FWL - Section 19, T31N, R6W

5. Lease Designation and Serial No.

SF 078988

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agmt. Design.:

Northeast Blanco Unit

8. Well Name and No.:

N.E.B.U. #323

9. API Well No.:

30-045-31023

10. Field & Pool/Exploratory Area:

Basin Dakota/Mesaverde

11. County or Parish, State:

San Juan, New Mexico

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION	
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Abandonment	<input type="checkbox"/> Change of Plans
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion	<input type="checkbox"/> New Construction
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Altering Casing	<input type="checkbox"/> Conversion to Injection
	<input checked="" type="checkbox"/> Other: Bottom Hole Pressure Measurement	
	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

13. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Bottom Hole Pressure Measurement result taken August 23, 2002: 3326 psig at a depth of 7875 feet.

14. I hereby certify that the foregoing is true and correct.

Signed: Chuck Freier **CHUCK FREIER**

Title: **Company Representative**

Date: **10/10/2002**

(This space for Federal or State office use)

Approved by _____

Title _____

Date _____

Conditions of approval, if any: