

X		

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency Navajo

Window Rock, Arizona

Allottee _____

Lease No. Navajo Tribal
Contract I-149-Ind-7653

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL _____	SUBSEQUENT REPORT OF WATER SHUT-OFF _____	X
NOTICE OF INTENTION TO CHANGE PLANS _____	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING _____	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF _____	SUBSEQUENT REPORT OF ALTERING CASING _____	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL _____	SUBSEQUENT REPORT OF REDRILLING OR REPAIR _____	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE _____	SUBSEQUENT REPORT OF ABANDONMENT _____	
NOTICE OF INTENTION TO PULL OR ALTER CASING _____	SUPPLEMENTARY WELL HISTORY _____	
NOTICE OF INTENTION TO ABANDON WELL _____		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 26, 19 61

Well No. 1-3 is located 1430 ft. from N line and 660 ft. from W line of sec. 3

SW/4 NW/4 Section 3
(1/4 Sec. and Sec. No.)

T-30-N
(Twp.)

R-17-W
(Range)

N M P M
(Meridian)

Wilcoit
(Field)

San Juan County
(County or Subdivision)


New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded well at 5:50 PM Saturday June 24th. Set 67' of 7 5/8" 26# J-55 casing at 73' and cemented with 35 sac. Cement circulated. W-O-C. Tested casing w/500# for fifteen minutes. Test O. K.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Ken Blackford

Address P. O. Box 1527

Farmington, New Mexico

By Ken Blackford

Title Operator