



STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT
OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE

TONEY ANAYA
GOVERNOR

1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO 87410
(505) 334-6178

December 20, 1985

Mr. Rex Hitchcock
Arco Oil & Gas Co.
1816 E. Mojave
Farmington, NM 87401


Re: Horseshoe Gallup Unit #253 N-04-30N-16W
Horseshoe Gallup Unit #126 D-05-30N-16W
Horseshoe Gallup Unit #134 H-05-30N-16W
Horseshoe Gallup Unit #267 F-09-30N-16W
Horseshoe Gallup Unit #180 D-34-31N-16W
Horseshoe Gallup Unit #192 F-34-31N-16W
Horseshoe Gallup Unit #201 L-34-31N-16W
Horseshoe Gallup Unit #69 C-14-31N-17W

Dear Mr. Hitchcock:

Annual mechanical integrity tests on the referenced water injection wells indicate casing or packer leaks. In order to insure the protection of hydrocarbon and fresh water zones, you are hereby directed to initiate remedial action within 60 days.

If you have any questions, please contact this office.

Yours truly,


Carolyn J. Taplin
Field Representative

CJT/dj

xc: Well Files
Operator File
UIC File
Prentiss Childs