

## U.S. ENVIRONMENTAL PROTECTION AGENCY NOTICE OF INSPECTION

MECHANICAL INTEGRITY TEST

U. S. EPA REGION IX 75 Hawthorne St., W-6-2 San Francisco, CA 94105 OPERATOR: Vantage Point Energy WELL NAME: #126

API#: FIELD: Horseishue Gallup Unit

Notice of Inspection is hereby given according to Section 1445(b) of the Safe Drinking Water Act (U.S.C. Section 300f et seq.).

## REASON FOR INSPECTION

For the purpose of inspecting and witnessing the mechanical integrity test to determine whether the person subject to an applicable underground injection control program is acting in compliance with the Safe Drinking Water Act and any applicable permit or rule.

Note: Section 1445(b) is quoted in full on the reverse side of this form.

Receipt of this Notice of Inspection is hereby acknowledged.

FIRM REPRESENTATIVE

INSPECTOR(S)

In the event of an MIT failure, the operator is advised that the regulations require that a written description of the situation (and the approximate time needed to remedy it) is forwarded to the EPA within five days of the failure.