

(SUBMIT IN TRIPLICATE)

Indian Agency

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee

Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

RECEIVED

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

JUN 18 1958

U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

June 18

Well No. 1 is located 425 ft. from ☒ line and 202 ft. from ☒ line of sec. 34

SW/4 Sec. 34
(1/4 Sec. and Sec. No.)

31N
(Twp.)

16W
(Range)

101M
(Meridian)

Undesignated
(Field)

San Juan
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 5402 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

5-29-58 . TOTAL DEPTH 1425' .

Ran 33 joints 5-1/2", 15.50#, J-55 casing (1399.66') set at

1406.106' with 100 sacks regular cement, 4 o/b gal., 1/4 # Flocele per

sack. Held 1000# for 30 minutes.

Calculated top of cement at 770' .

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Banner Drilling Company

Address P.O. Box 1571

Farmington

New Mexico

By Banner
Title Co Owner

