5. LEASE

14-20-604-90

## UNITED STATES DEPARTMENT OF THE INTERIOR

GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	UTE MOUNTAIN UTE
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
Do not use this form for proposals to drill or to deepen or plug back to a different eservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
	Ute Mountain "B"
1. oil gas other	9. WELL NO.
2. NAME OF OPERATOR	# 4
Chase Energy, Inc.	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Verde Gallup
2501 E. 20th Street, Farmington, N. M.	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA
below.) AT SURFACE: 1980' fnl, 1980' fwl	Sec. 32, T31N, R15W
AT TOP PROD. INTERVAL:	12. COUNTY OR PARISH 13. STATE
AT TOTAL DEPTH: "	San Juan N.M.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. AFI NO.
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
·	5422 Gr.
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	
FRACTURE TREAT	
REPAIR WELL	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING	change on Form 9-330.)
MULTIPLE COMPLETE	•
ABANDON*	
(other) OTHER	
including estimated date of starting any proposed work. If well is a measured and true vertical depths for all markers and zones pertiner.  As a result of the meeting on Septer representatives of the BLM, BIA and Chass conclusions reached concerning the pittic Chase hereby requests permission to use 1320' south which is approximately 65' x.  The use of this pit which already essity of digging another pit on the local turbance of the lease. Since there is not be at 1835.2' once the water is pumped well should not make any water. The Verdoes not produce water. The water came packing it off, the operator feels that to production.  Subsurface Safety Valve: Manu. and Type	ember 30, 1987, between see Energy, Inc. and the eng of produced water, the existing pit located 44' and over 6' deep. exists eliminate the nectation and further distance a packer set in this loff the formation, the ede Gallup on this lease from up-hole and by the well can be returned
18. I hereby certify that the foregoing is true and correct	
SIGNED David Compsey TITLE President	DATE12/26/87
(This space for Federal or State of	fice use)
APPROVED BY L. Mark Hollis	EB 1 1988
CONDITIONS OF APPROVAL, IF ANY:	EGEINEW
<b>\$</b> TIPI机。tuma s	FER O.2 18Pa
*See Instructions on Reverse	Side Antonio A

NMOCD



Realty

## United States Department of the Interior

## **BUREAU OF INDIAN AFFAIRS**

UTE MOUNTAIN AGENCY
TOWAOC, COLORADO 81334

RECEIVED

Burness of Land Meneggenters

JAN 2 2 1988

JAN 281988

Durango, Colorado

## **MEMORANDUM**

TO

: Bureau of Land Management, San Juan Resource Area

Attention: Oil and Gas Division

FROM

: Superintendent, Ute Mountain Ute Agency

SUBJECT:

Request to Dispose Produced Water from the Ute Mountain "B" #4 Well

Well on Lease 14-20-604-90

On September 30, 1987, a field inspection was conducted to determine whether an existing pit could be used for disposal of produced water from the #4 "B" Well. We will require that the pit be fenced to keep livestock out and the northeast corner of pit be repaired to prevent surface water from entering the pit.

If Chase Energy Inc. has submitted their application to dispose of produced water in a unlined pit in accordance with NTL-2B and BLM approves their application we have no objection. We are requesting a copy of the approved application be provided to our Realty Office.

Superintendent

