



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. SF-080917
Unit H₂ Sec. 34

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	<u>Subsequent Report of Test</u>	<u>X</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Sept. 30, 1963

Delhi-Atlantic
Well No. 1-34 is located 990 ft. from N line and 990 ft. from E line of sec. 34

NE₁ Sec. 34 T31N R10W N.M.P.M.
($\frac{1}{4}$ Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Basin Dakota San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of ~~the wellhead from base of well~~ is 6282 ft. G.L.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Moved in workover rig, killed well with salt water, pulled tubing, set Halliburton bridge plug at 5712'. Ran cement bond log and no indication of cement over none. Perforated 5590-91' with four holes and squeezed 75 sacks cement. Re-squeezed perforation with 50 sacks cement. Cleaned out cement, jet perf. with one hole per foot 5547-54' and 5558-59'. Ran Halliburton KTS tool with retrievable valve tester set at 5520'. Recovered tools. Reset KTS packer and squeezed perforations 5547-57' with 50 sacks. Cleaned out cement. Re-ran 250 jts. of 2-3/8" 4.70# tubing, landed at 7432'. Installed Xmas tree and now swabbing well to clean prior to being S.I.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Delhi-Taylor Oil Corporation

Address P. O. Drawer 1198

Farmington, New Mexico

Original signed by
A. R. Gibson

By A. R. Gibson
Title Dist. Supt.

