

(Submit in triplicate)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Company LEASE NO. 231467
UNIT _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL _____	SUBSEQUENT REPORT OF WATER SHUT-OFF _____
NOTICE OF INTENTION TO CHANGE PLUMS _____	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING _____
NOTICE OF INTENTION TO TEST WATER SHUT-OFF _____	SUBSEQUENT REPORT OF ALTERING CASING _____
NOTICE OF INTENTION TO REPAIR OR REPAIR WELL _____	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR _____
NOTICE OF INTENTION TO SHUT OR ACIDIZE <u>FROM</u> <u>X</u> _____	SUBSEQUENT REPORT OF ABANDONMENT _____
NOTICE OF INTENTION TO DILL OR ALTER CASING _____	SUPPLEMENTARY WELL HISTORY _____
NOTICE OF INTENTION TO ABANDON WELL _____	_____

INDICATE LEADS BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA

Uti Indian Tribe WPA

January 16, 1961

WELL NO. 4 IS LOCATED 990 FT. FROM (N) LINE AND 660 FT. FROM (E) LINE OF SEC. 36

NE 1/4 of NW 1/4 31 36-W NM 1961
(SECTION) (TWP) (RANGE) (MERIDIAN)
Grade Gallup San Juan New Mexico
(FIELD) (COUNTY OR SUBDIVISION) (STATE OR TERRITORY)

THE ELEVATION OF THE DRAINAGE FLOOD ABOVE SEA LEVEL IS 5606 FT.

DETAILS OF WORK

(GIVE ALL SIZE OF ANY EQUIPMENT USED TO DIRECTIVE CAMEL; SHOW SIZES, WEIGHTS, AND LENGTHS OF PROPOSED CASINGS; INDICATE MIDDING JOBS, BENTONITE JOBS, AND ALL OTHER IMPORTANT PROPOSED WORK.)

From (con 444) to 444 through bottom 90' of slotted 4" liner (at 120° angle) with 20,000 gals. (last) above, 10,000# sand and 110 gals 2-97.



UNDERSTANDING THAT THE PROPOSED WORKING IS SUBJECT TO THE GEOLOGICAL SURVEY REPORT OPERATIONS MAY BE COMMENCED.

Compton Oil & Gas Refining Company

Address: Box 2147, Lordsburg, New Mexico

ORIGINAL
SIGNED: ARVIN D. EADY

By _____

TITLE Agent