

(SUBMIT IN TRIPLICATE)

Indian Agency **NAV-028**

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Allottee **14-20-604-1951**  
Lease No. \_\_\_\_\_


SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	<b>SAND OIL FRAC.</b>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

November 5th, 1958


Well No. **3** is located **2310** ft. from **RM** line and **330** ft. from **W** line of sec. **33**  
**NE 1/4 Sec. 33** **11N** **10W** **NE 1/4**  
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
**Harvesting Alluv Est.** **San Juan** **New Mex.**  
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **5733** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

**11/5-58 Total Depth 1402'. Clean out T.D. 1386'**  
**Sand oil Free alluv. Perforated intervals 1315'-1342'**  
**(4 shale per ft.) With 30000 lbs. Sand and 35000 lbs. Oil Break**  
**Down Pressure 475 lbs.**  
**Maximum treating pressure 400 lbs. Injection Rate 45 bbls./min**  
**Flush 1500' als.**



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

**Banner Drilling Co.**

Company \_\_\_\_\_

**P.O. Box 1571**

Address \_\_\_\_\_

**Farmington, New Mexico**

By **Ben Banner**  
**Co-owner**

Title \_\_\_\_\_