

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency Navajo

Allottee _____

Lease No. 14-00-000-1257

SUNDRY NOTICES AND REPORTS ON WELLS

| | | |
|---|--|-------------------------------------|
| NOTICE OF INTENTION TO DRILL | SUBSEQUENT REPORT OF WATER SHUT-OFF | |
| NOTICE OF INTENTION TO CHANGE PLANS | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING | |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF | SUBSEQUENT REPORT OF ALTERING CASING | |
| NOTICE OF INTENTION TO REDRILL OR REPAIR WELL | SUBSEQUENT REPORT OF REDRILLING OR REPAIR | |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE | SUBSEQUENT REPORT OF ABANDONMENT | <input checked="" type="checkbox"/> |
| NOTICE OF INTENTION TO PULL OR ALTER CASING | SUPPLEMENTARY WELL HISTORY | |
| NOTICE OF INTENTION TO ABANDON WELL | | |

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 19, 1962

Well No. 25 is located 3650 ft. from N line and 2075 ft. from E line of sec. 36

SW NE Section 36 (1/4 Sec. and Sec. No.) 1 36N 19W (Twp.) (Range) (Meridian)

Wildcat (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 5200 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

to 5200'.

Well was plugged and abandoned as follows: 100' plug in surface which covers top of Gallup formation. A regulation dry hole marker was placed in top of cement. Location is clean and ready for inspection.



RECEIVED
SEP 1 1962

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Bumble Oil & Refining Company

Address P. O. Box 3082

Durango, Colorado

COPY (ORIGINAL SIGNED) B. M. BRADLEY

By B. M. Bradley

Title District Engineer