

			X

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency _____

Ute Mountain Tribal

Allottee _____

Lease No. 14-20-604-125

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	X
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Ute Mountain Tribal "E" Farmington, New Mexico March 17, 1960

Well No. 3 is located 660 ft. from N line and 2130 ft. from E line of sec. 35

NE 1/4 of Section 35 T-31-N R-15-W N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Verde Gallup San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5434 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Ute Mountain Tribal "E" Well No. 3 was plugged and abandoned as follows on March 10, 1960, as a result of not obtaining oil or gas in commercial quantities:

1. Spotted 55 sacks cement plug in 5-1/2" casing 4153-4664 with final pressure 200 psi.
2. Filled hole with fluid.
3. Pumped 50 sacks of cement down 5-1/2" - 8-5/8" annulus to anchor pipe.
4. Removed wellhead and surface equipment.
5. Spotted 5 sacks of cement for surface plug (0-40') and erect dry hole marker.
6. Plug and abandonment operations by above procedure to permit possible re-entry for future secondary recovery purposes.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Pan American Petroleum Corporation

Address Box 487

Farmington, New Mexico

Attn: L. O. Speer, Jr.

ORIGINAL SIGNED BY
R. M. Bauer, Jr.

By _____

Title Area Engineer

