submitted in lieu of Form 3160-5

**UNITED STATES**
**DEPARTMENT OF THE INTERIOR**
**BUREAU OF LAND MANAGEMENT**

Sundry Notices and Reports on Wells

| | |
|---|---|
| | **5. Lease Number** 14-20-604-1950 |
| **1. Type of Well**    X   Oil      Gas      Other | **6. If Indian, Allotee or Tribe name** Ute |
| **2. Name of Operator** Vantage Point Operating Company | **7. Unit Agreement Name** Horseshoe Gallup |
| **3. Address & Phone No. of Operator** 2401 Fountain View Drive Suite 700 Houston, TX 77057-4862 (713) 780-1952 | **8. Well Name & Number** HGU #185 |
| | **9. API Well No.** 30-045-10211 |
| | **10. Field and Pool** Horseshoe Gallup |
| **4. Location of Well, Footage, Sec., T, R, M** C-35-31N-16W 660' FNL & 1980' FWL | **11. County and State** San Juan, New Mexico |

RECEIVED AUG 1 2 1994 OIL CON. DIV. DIST. 3

**12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA**

| Type of Submission | Type of Action | | | |
|---|---|---|---|---|
| X   Notice of Intent | ___ | Abandoment | ___ | Change of Plans |
| | ___ | Recompletion | ___ | New Construction |
| ___ Subsequent Report | ___ | Plugging Back | ___ | Non-Routine Fracturing |
| | ___ | Casing Repair | ___ | Water Shut Off |
| ___ Final Abandonment | ___ | Altering Casing | ___ | Conv. to Injection |
| | ___ | Dispose Water | | |
| | X | Other - LTSI | | |

**13. Describe Proposed or Completed Operations**

This well is currently shut-in.
Vantage is requesting LTSI status from the BLM until such time it is economically feasible to return this well to production.

THIS APPROVAL EXPIRES AUG 0 1 1995

94 JUL 22 PH 2:22 070 FARMINGTON, NM RECEIVED BLM

**14. I Hereby certify that the foregoing is true and correct.**

Signed _Dianna K. Fairhurst_    Title Consulting Engineer    Date 7/13/1994
'Dianna K. Fairhurst

(This Space for Federal or State Office Use)
**APPROVED BY :** _____ Title _____ Date _____

CONDITION OF APPROVAL, if any: _____ APPROVED

AUG 08 1994 Chip Harraden for DISTRICT MANAGER

NMOCD