

(SUBMIT IN TRIPLICATE)


Indian Agency

Ignacio

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee **Ute Mtn. Tribal**

Lease No. **14-20-604-1950**



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	MAR 3 1961
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....	Subsequent report of perforating and treating	x

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 27, 19 61

Well No. **Ute #7** is located **1980** ft. from **N** line and **660** ft. from **W** line of sec. **35**

SW NW Sec 35 (¼ Sec. and Sec. No.)	T-31-N R-20-W (Twp.) (Range)	NMPM (Meridian)
Horseshoe Gallup (Field)	San Juan (County or Subdivision)	New Mexico (State or Territory)

The elevation of the ~~corner floor~~ **ground** above sea level is **5453.0** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Cut notches at 1368 and 1370' Gamma Ray with Dowell AbrasiJet tool. Treated above notches with 35,800 gals lease crude containing 50,000% of 10/20 sand. FBD 1400%. Average treating pressure 1500%. Average injection rate 30 barrels per minute.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **The Atlantic Refining Company**

Address **P. O. Box 520**

Casper, Wyoming

By *C. W. Leaphin*

Title **Regional Drilling Manager**

