UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

			-		7.	0.1
1.	٠.	- 1	i	2 -	≟•	

Sund	dry Notices and Reports	on Wells			
		5. Lease N	umber		
		14-20-60	4-1950		
1. Type of Well	6. If Indiar	6. If Indian, Allotee or Tribe name			
X OilGasOthe	Ute				
2. Name of Operator	1 -	7. Unit Agreement Name			
Convest Energy Corporation		Horseshoe Gallup			
3. Address & Phone No. of Operator	1	3. Well Name & Number ∃GU #195			
2401 Fountain View Drive		. API Well No.			
Suite 700	1	0-045-10215 D. Field and Pool forseshoe Gallup			
Houston, TX 77057-4862	<u> </u>				
(713) 780-1952					
Location of Well, Footage, Sec., T, R,	<u> </u>				
E-35-31N-16W			11. County and State San Juan, New Mexico		
1980' FNL & 600' FWL /9/0 - 66 0	Sali Juai	Sali Juali, New Mexico			
12. CHECK APPROPRIATE BOX(s) TO II	NDICATE NATURE OF I	NOTICE, RE	PORT, OTHER DATA		
Type of Submission	Type of Acti	on			
	Abandonment		Change of Plans		
X Notice of Intent	Recompletion		New Construction		
	Plugging Back		Non-Routine Fracturing	3	
Subsequent Report	Casing Repair		Water Shut Off		
 · · · 	Altering Casing		Conv. to Injection		
Final Abandonment	Dispose Water				
X	Other - Return to Pi	roduction			
13. Describe Proposed or Completed O	perations				
This well was returned to production	n on 02/13/95.				
				er een ee	
			$f_{-a} = f_{-a}$		
				* **	
			,		
14. I Hereby certify that the foregoing is	true and correct.				
Signed Wlama K. (h.k.) Dianna K. Fairhurst	LK소는 Title Consulting E	ngineer	Date 04/03/95		
(This Space for Federal or State Office Use	•		ADDERTED DATE	D=66	
APPROVED BY :	Title		AGCEPTED FOR	KECO	
CONDITION OF APPROVAL, if any:		APR 1 3 19	95		
			1, ~ 0 100		
			FARIAMETON BAGGE		