


(SUBMIT IN TRIPLICATE)

Indian Agency **NAV-UTE**

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Allottee

Lease No. **14-20-604-1951**



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	<b>SAND OIL FRAC.</b>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

**November 10**, 19**58**

Well No. **4** is located **999** ft. from **[N]** line and **330** ft. from **[E]** line of sec. **33**  
**EE: Sec 33** **51N** **16 E**  
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
**Horseshoe alluv Exl.** **San Juan** **New Mexico**  
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **3403** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

**6/5-58** Total depth **1400** Ft. Clean out T.D. **1385** Ft.

**Sand Oil Frac** alluv. Perforated intervals **1246' - 1280**


(4 shots per Ft.) with **33600** lbs oil and **30,000** sand

**BREAK DOWN PRESSURE 1050 LBS.**

**MAXIMUM TREATING PRESSURE 700 LBS.**

**INJECTION RATE 42 Bbls./ min.**

**FLUSH 1600 ALS.**



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Banner Drilling Co.**

Address **Box 1571**

**Farmington,**

**New Mexico**

By **Ben Banner**  
**Co. owner**

Title