

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OIL COM. DIV.

	Sundry No	tices and Repo	ts on Wells				
				se Number			
1. Type of Well				14-20-604-1951			
X Oil Gas Other				6. If Indian, Allotee or Tribe name Ute			
2. Name of Operator Vantage Point Operating Company				7. Unit Agreement Name			
3. Address & Phone No. of Operator				Horseshoe Gallup			
2401 Fountain View Drive				8. Well Name & Number HGU #177			
Suite 700			9. API				
Houston, TX 77057-4862				30-045-10237			
(713) 780-1952			<u> </u>	10. Field and Pool			
4. Location of Well, Footage, Sec., T, R, M				Horseshoe Gallup			
C-33-31N-16W				11. County and State			
645' FNL & 3170' FEL			•	San Juan, New Mexico			
							
12. CHECK APPROPRIATE BOX(s) TO INDICA			REPORT, O	THER DAT	Ά	
Type of Submission		Type of A	ction				
X Notice of Intent		bandoment		Change			
A Notice of filterit		Recompletion			struction		
Subsequent Report		lugging Back asing Repair		Non-Rou Water St	tine Fractu	ınng	
ouboduone respon		Itering Casing	·	Conv. to			
Final Abandonment		ispose Water		Conv. to	mjection		
		ther - LTSI					
13. Describe Proposed or Comple	eted Operation	ons					
This well is currently shut-in.	ı .				0	9	
Vantage is requesting LTSI status from the BLM until such time			n time it is		7	<u>.</u>	
economically feasible to retu	um this well to	production.			₹	⋈	7
					070 FARMINGTON,	94 JUL 22	ארני פארני
	HS APPROM	(1) 经水面(成 次)	VIG 0 1 1995)	₹		
in	119 VLAMOR	AP MALHUEA			ö	PH	~~
٠					Ž,	Ň	ED
					3	N	
					-		
14. I Hereby certify that the foreg	oing is true a	ind correct.					
Signed Suarro K. Jo 'Dianna K. Fairhurs		Title Consulting	Engineer	Date	7/13/1994		
(This Space for Federal or State Off	fice Use)						_
APPROVED BY :		Title		Date			
							
CONDITION OF APPROVAL, if any	<i>/</i> :		· · · · · · · · · · · · · · · · · · ·			<u> </u>	
				A	PPH	UV	
						• • • • •	7 4