


(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe  
Lease No. 111 0606  
Unit W/ 2 Sec. 27



SUNDRY NOTICES AND REPORTS ON WELLS

RECEIVED  
AUG 28 1957

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR CHARGING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	<input checked="" type="checkbox"/>		

U. S. GEOLOGICAL SURVEY  
FARMINGTON, NEW MEXICO

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

~~REPORT~~ August 26, 19 57

Well No. Atlantic is located 790 ft. from S line and 990 ft. from W line of sec. 27

SEA Sec. 27 (1/4 Sec. and Sec. No.) 12N (Twp.) 2E (Range) 109W (Meridian)  
Wilcox (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 4337 ft. 6.15

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

After several unsuccessful attempts to whipstock hole and re-complete well, we propose to P & A by spotting approx. 50 cu. cement plug from 5 1/2" Casing stub at 4200' back into 7 5/8" Casing, set at 4712, and to spot cement plugs from point of recovery of 7 5/8" Casing to surface, subject to approval of U.S.G.S. representative.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Bulhi-Taylor Oil Corporation

Address P. O. Box 1175

Farmington, New Mexico

By

Title

Dist. Supt.

