


STATE OF NEW MEXICO
OIL CONSERVATION
COMMISSION
DISTRICT NO. 3
Phone 99 P. O. Box 697
AZTEC, NEW MEXICO

(SUBMIT IN TRIPLICATE)
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Santa Fe
Land Office 000376
Lease No. 248476
Unit



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 13, 1951

Well No. 1 is located 900 ft. from N line and 1000 ft. from E line of sec. 28
SS ON Section 28
(1/4 Sec. and Sec. No.)
Blanco Extension (Twp.) San Juan (Meridian) New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6164 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On July 11, 1951:

Run 105 joints of 6-5/8", 20 lb., J-55 casing set at 4550' with two stage cement procedure. Tool at 383'.

First Stage - 150 sacks Ideal Regular and 2 sacks Floccol.

Second Stage - 150 sacks Ideal Regular and 1 sack Floccol.

Temperature Survey on Second Stage top 1600'

Hold 2,000 lbs. for 15 minutes.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company TOM BLAKE & SAN JUAN PRODUCTION COMPANY


Address 100 1/2 North Court Avenue

Pennington, New Mexico

By

Petroleum Engineer

Title



DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
UNITED STATES
(SUBMIT IN TRIPlicate)

Land Office _____
Lease No. _____
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO ABANDON WELL	
NOTICE OF INTENTION TO PULL OR LIFT CASING	
NOTICE OF INTENTION TO SHOOT OR REPAIR	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	
NOTICE OF INTENTION TO DRILL	
SUPPLEMENTARY WELL HISTORY	
SUBSEQUENT REPORT OF ABANDONMENT	
SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
SUBSEQUENT REPORT OF ALTERING CASING	
SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
SUBSEQUENT REPORT OF WATER SHUT-OFF	

(INDICATE ABOVE BY CHECKING NATURE OF REPORT, NOTICE OR OTHER DATA)

_____ is located _____ ft. from _____ N _____ E
_____ and _____ ft. from _____ W _____ E
_____ line of sec. _____
(State or Territory) (County) (Range) (Section)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and specify depths to objectives in object of work and details of proposed casing, tubing and log job in work.)
(In bold type, indicate important proposed work.)

I understand that this plan of work must receive approval of the Geological Survey before operations may be started.
Company _____
Address _____
By _____
Title _____