

OIL CONSERVATION COMMISSION
1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO

July 21, 1966

El Paso Natural Gas Company
Box 990
Farmington, New Mexico

Attn: Mr. William Cutler

Re: El Paso Natural Gas Co.
#1 Sheets, N-28-31-9

Dear Mr. Cutler:

Bradenhead test submitted for the above well on July 13, 1966 indicates that there is communication between the bradenhead and production casing on this well. It appears evident that the production casing has failed.

We therefore direct that immediate remedial action be taken on this well.

Yours very truly

Emery C. Arnold
Supervisor, District #3

ECA:ks

cc: Oil Conservation Commission
Santa Fe, New Mexico

*Repaired
Aug. 66
Well file*

THE CONSERVATION COMMISSION
1800 RIO SAN JOSE ROAD
SANTA FE, NEW MEXICO

Dear Mr. [Name]:
I am writing to you in response to your letter of [Date] regarding the [Subject]. I am sorry that I cannot provide you with a more definitive answer at this time, but the [Subject] is a complex issue that requires further investigation and consultation with our [Subject] experts.

Very truly,
[Signature]

I am sure that you will understand the need for thoroughness in this process. We will keep you informed as soon as a final decision has been reached. Thank you for your patience and understanding.

Very truly,
[Signature]
[Name]
[Title]
[Address]
[City, State, Zip]

cc: [Name]
[Address]
[City, State, Zip]

cc: [Name]

Enclosed for you are two copies of the [Subject] report. I am sure that this information will be helpful to you in your [Subject] efforts. If you have any questions or need further assistance, please do not hesitate to contact me.

We look forward to your response and to continuing our [Subject] efforts together.

Yours very truly,
[Signature]

Very truly,
[Signature]
[Name]
[Title]
[Address]
[City, State, Zip]

cc: [Name]

cc: [Name]
[Address]
[City, State, Zip]

NEW MEXICO OIL CONSERVATION COMMISSION
1000 Rio Brazos Road
Aztec, New Mexico

BRADENHEAD TEST REPORT
(Submit 3 copies to above address)

*Leak. notified to repair
oper. 7-21-66
can*

Date of Test 6-16-66 Operator EPNG

Lease Name Sheets Well No. 1 Location U N Sec. 28 Twp. 31 Rge. 9

Pressure (~~Shot in or~~ Flowing) Dwt. Tubing 514 Casing 305 Bradenhead 250

OPEN BRADENHEAD TO ATMOSPHERE FOR 15 MINUTES.

Casing or ~~Testing~~ Pressure, Dwt.


Bradenhead Flowed:

5 Min. <u>245</u>	X	Steady Flow <u> </u>
10 Min. <u>235</u>		Surges <u> </u>
15 Min. <u>235</u>		Down to Nothing <u> </u>
20 Min. <u>235</u>		Nothing <u> </u>
25 Min. <u>235</u>		Gas <u> </u>
30 Min. <u>235</u>		Gas & water Oil <u>X</u>
		Water <u> </u>

If Bradenhead flowed water check description below:

Clear
Fresh
Salty
Sulfur
Black X

Remarks:



By Harold Hicks

Gas Tester

Position

Witness