

OIL CONSERVATION COMMISSION

1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO

October 8, 1962

*El Paso Natural Gas Company
Box 990
Farmington, New Mexico*

Attn: Mr. E. S. Oberly

*RE: EPNG #9-A Atlantic,
N-27-31N-10W*

Dear Sir:

Bradenhead test for the above well received October 5, 1962 shows evidence of casing failure.

You are, therefore, directed to take immediate action to repair the casing in this well. Please submit Form C-102 to this office, outlining the remedial work to be accomplished, before commencing operations.

Yours very truly

*Emery C. Arnold
Supervisor, District #3*

ECA:ks

cc: U.S.G.S., Farmington, N.M.

N.M.O.C.C., Santa Fe, N.M.

NEW MEXICO OIL CONSERVATION COMMISSION
1000 Rio Brazos Road
Aztec, New Mexico

BRADENHEAD TEST REPORT
(Submit 3 copies to above address)

Date of Test 10-2-62 Operator El Paso Natural Gas Company
Lease Name Atlantic Well No. 2-A Location U N Sec. 27 Twp. 31 Rge. 10
Pressure (~~Shut-in~~ Flowing) Dwt. Tubing 495 Casing 637 Bradenhead 653

OPEN BRADENHEAD TO ATMOSPHERE FOR 15 MINUTES.

Casing or ~~Tubing~~ Pressure, Dwt.

Bradenhead Flowed:

5 Min. 635 - 35 Min. 629
10 Min. 633 - 40 Min. 628
15 Min. 632 - 45 Min. 628
20 Min. 631 - 50 Min. 627
25 Min. 630 - 55 Min. 627
30 Min. 629 - 60 Min. 626
1 hour = 492 tubing

Steady Flow X
Surges _____
Down to Nothing _____
Nothing _____
Gas X _____
Gas & Water _____
Water _____

If Bradenhead flowed water check description below:

Clear _____
Fresh _____
Salty _____
Sulfur _____
Black _____

Remarks: Diff. dropped from 5.0 to 4.6
during blow.

By Gary R. Candy

tester

Position

Witness W. B. Smith (OCC)

