


(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency Ute Mountain Tribal
Allottee 14-20-60-84
Lease No. 14-20-60-84



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

RECEIVED

NOV 10 1959

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

Nov. 9, 1959


Well No. 6 is located 1630 ft. from N line and 1980 ft. from E line of sec. 30
NW SE Sec. 30 31N 14W R4E
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Vorio Gallup San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5347 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded 2:30 a.m. 11-6-59. Drilling 11" hole to 142 feet. Ran 4 jts. 126.93' of 8-5/8" O.D. Std 24 1/2 2-55 R-2 Spang wils. cas. set @ 141.50' R.D. w/30 sz 2# calcium chloride. Plug down 11:15 a.m. 11-6-59. Cement circulated. W.O.C. 24 hours. Tested plug w/300 psi for 30 min. Test OK.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Three States Natural Gas Company

Address Box 67

Farmington, New Mexico

By Original Signed By John Carothers

Title Assistant District Supt.

