

(SUBMIT IN TRIPLICATE)

Indian Agency


UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee _____

Lease No. 14-20-604-1001

		X	

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<div style="text-align: center;">  <p>RECEIVED</p> <p>JUL 27 1964</p> </div>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

July 24 19 59

Keywords

Well No. 17 is located 660 ft. from S line and 1900 ft. from E line of sec. 23

SW 22/4 Section 28
(4 Sec. and Sec. No.)

21N
(Twp.)

LOW
(Range)

NACF

Marquette College Inst.
(Field)

Don Jones

New Member

The elevation of the derrick floor above sea level is 5734 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

July 21, 1960 Trawl Depth 1731'.

Run 42 joints, 8-1/2", 15,500, J-55 Casing (1740') set at 1731'
with 25 sacks regular cement, 25 sacks Peamix, 4% Gel., 1/40
Fluents per sack.

Field 19994/30 Minnesota.

Top of cement by temperature survey at 925'.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas Products Company

Address Post Office Box 1548

Pennington, New Mexico

ORIGINAL SIGNED BY: JOSEPH E. KREGER
By _____

Title **Petroleum Engineering**



JOSEPH E. KREGER