

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency _____

Pto Navajo

Allottee _____

Lease No. **34-22-004-1951**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

RECEIVED
OCT 12 1959

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

10-10-1959

U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

Well No. **5** is located **1670** ft. from **S** line and **330** ft. from **W** line of sec. _____
SW 1/4 27 **31N** **26W** **RPM**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Hartshorn Gallup **San Juan** **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **7629** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

10-5-59 **Perf 1520-1490, 4 bullets per ft., sand oil free**
93,000' sand, 1,320 lbs less crude



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Petro Atlas Inc**

Address **P.O. Box 1976**

Farmington, New Mexico

By **Louise Clamer**

Title **Asst.**

