

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget ~~Number~~ **14-20-404-1951**
Approval ~~Signature~~ **14-20-404-1951**

Indian Agency _____

Allottee **14-20-404-1951**

Lease No. _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 11 1959

Hercules Ute
23

1900

XX

660

19 28

Well No. _____ is located **31N** ft. from **[N]** line and **10W** ft. from **[W]** line of sec. **28**

Hercules Ute

(Twp) **San Juan** (Range)

(Meridian)

New Mexico

(Field)

(County or Subd) **San Juan**

(State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

9-8-59 Total Depth 1768'

Ran 44 joints 2-1/2", 15.500, J-55 Casing (1760.20') set at 1767.20' with 50 sacks regular cement, 50 sacks Pozmix, 4% gel., 1/4" Floccul per sack.

Held 10000/30 Minutes.

Top of cement by temperature survey at 900'.



I understand that this well is being drilled by the Geological Survey before operations may be commenced.


Company **Rock Office Box 1345**

Address **Farmington, New Mexico**

ORIGINAL SIGNED BY: **WILLIAM K. GLAZENER**

By **Petroleum Engineer**

Title _____



RECEIVED BY THE POST OFFICE