Ferm 3160-5

LINITED STATES

SUBMIT IN TRIPLICATE.

Form approved.

Budget Burgau No. 1004-1133

	ovember 1983) ormerly 9-331)	DEPARTMENT O	OR (Other instructions on reverse side)	5. LEASE DESIGNATION	AND BREIAL NO	
	SUN	NDRY NOTICES AN	ND REPORTS (ON WELLS	6 IF INDIAN, ALLOTTE	03-2037 E OR TRIBE NAME
,	(Do not use this	s form for proposals to drill Use "APPLICATION FOR	or to deepen or plug t PERMIT—" for such p	PECEIVED	Navajo	V.
•	OIL GAS WELL					
2.	WELL X WELL NAME OF OPERATOR	OTHER		NOV 1 0 1986	Horseshoe 8. FARM OR LEASE NAI	Gallup Unit
	ARCO Oil and	d Gas Company			Horseshoe	Gallup Unit
3.	ADDRESS OF OPERATO	0.8		BUREAU OF LAND MANAGEMENT	9. WBLL NO.	ANTIAP OUT
١.	P. O. Box 16	610. Midland, Texa Report location clearly and in low.)	s 79702 accordance with any	FARMINGTON RESOURCE AREA State requirements.	10. FIELD AND POOL O	R WILDCAT
	See also space 17 bel At surface	Unit " I	11		W	a 11
			1		Horseshoe 11. smc., r., s., m., or r survey or area	GALLUD BLE. AND
	2310'	FSL & 330' FEI	L, Sec. 25			
					Sec 25-3	1N-17W
	PERMIT NO.	4	IONS (Show whether DF	, RT, GR, etc.)	12. COUNTY OR PARISH	13. STATE
Vo	API NO. A	ssigned 57	762' GR		San Juan	N M
6.		Check Appropriate	Box To Indicate N	lature of Notice, Report, or O	ther Data	
		NOTICE OF INTENTION TO:		SUBSEQU	ENT EMPORT OF:	
	TEST WATER SHUT-OFF PULL OR ALTER CASING			WATER SHUT-OFF	T REPAIRING T	WELL
	FRACTUBE TREAT	MULTIPLE CO	MPLETE	FRACTURE TREATMENT	ALTEBING C.	ASING
	SHOOT OR ACIDIZE	ABANDON®		SHOOTING OR ACIDIZING	ABANDONME	NT* X
	REPAIR WELL	CHANGE PLAN	۶	(Other)		
	(Other)		1	(Note: Report results Completion or Recomple	of multiple completion tion Report and Log for	on Well
7. i	proposed work. If nent to this work.)	R COMPLETED OPERATIONS (Cle well is directionally drilled,	nally state all pertinent give subsurface locat	details, and give pertinent dates, ions and measured and true vertica	including estimated dat depths for all marker	e of starting any s and zones perti-
	,					
	This we	ll was plugged	10/30/84 -	11/1/84 as follows	s: Con 1000	in said an
	<u>Plug</u>	<u>Interval</u>	<u>Cement</u>		1000	Marian Marian
	1	1233 - 1498	30 sx	Spotted plug to 1399 - 1425 and	cover Gellu 1479 - 98.	p perfs
	2	850 - 950	30 sx	Squeezed 2 perfeisolate the TOC 1100'. Left a	from Temp S	urvey at

1	1233 - 1498	30 sx	Spotted plug to cover Gallup perfs 1399 - 1425 and 1479 - 98.
2	850 - 950	30 sx	Squeezed 2 perforations at 950' to isolate the TOC from Temp Survey at 1100'. Left a 100' cement plug inside the 5-1/2" casing.
3	50 - 150	30 sx	Squeezed 2 perforations at 150' to isolate the surface casing shoe at 122'. Left a 100' plug inside the 5-1/2" casing.
4	0 - 30	5 sx	Spotted a 5 sk plug at surface.

Welded a steel plate over the top & installed a dry hole marker.

-			AND AND AND ADDRESS OF THE CONTRACT OF THE PROPERTY OF THE PRO	
18.	SIGNED Ken W Lornel	915-688-5672 FITLE Engr. Tech. Spec.	DATE 11-7-82	
==	(This space for Federal or State office use)			
	APPROVED BY		DATE	
	CONDITIONS OF APPROVAL, IF ANT:	Approved as to plantage of the trell bare. Listing as the plantage of the trell bare. Surface you to take to	FRANCE	
		*See Instructions on Reverse Side	FARMING TON FASSILLAND SILES	

NMOCC