


BURLINGTON RESOURCES

SAN JUAN DIVISION

February 5, 1998

Denny Foust
New Mexico Oil Conservation Division
1000 Rio Brazos Road
Aztec, NM 87410

**Re: Wilmuth #1
Bradenhead Test Report**



Mr. Foust:

Per your request, attached is a copy of the most recent Bradenhead Test Report for the subject well. I also wanted to inform you that the pumping unit at this location has been down since December 31, 1997. If you have any questions concerning this, please contact me at 326-9841.

Sincerely,

A handwritten signature in cursive script, appearing to read "Ed Hasely".

Ed Hasely
Sr. Staff Environmental Representative

cc: Correspondence

STATE OF NEW MEXICO
ENERGY and MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
1000 Rio Brazos Road
Aztec, New Mexico

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 9-11-96 Operator MERIDIAN OIL CO.

Lease Name WILMUTH Well No 1 Unit N Sec. 26 Twp. 031N Rge. 011W

Pressure (Shut-in/Flowing) Dwt Tubing 299 Intermediate NA CASING 408 BRADENHEAD 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME:	PRESSURES:		BRADENHEAD FLOWED:	INTERMEDIATE FLOWED:
	INTERMEDIATE	CASING		
5 Min.		<u>299</u>	Steady Flow	
10 Min.		<u>299</u>	Surges	
15 Min.		<u>299</u>	Down to Nothing	
20 Min.			Nothing	
25 Min.			Gas	
30 Min.			Gas & Water	
			Water	

If Bradenhead flowed water check description below:

Clear _____
Fresh _____
Salty _____
Sulfur _____
Black _____

Remarks: _____

By LE McInnes

A LEASE OPERATOR
position

NO 50159A

Witness _____