

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	5. LEASE DESIGNATION AND SERIAL NO. 14-20-604-1891
2. NAME OF OPERATOR Benson-Montin-Greer Drilling Corp.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME Ute Mountain Tribal
3. ADDRESS OF OPERATOR 221 Petroleum Center Building, Farmington, NM 87401	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface  960' FNL, 660' FWL, Sec. 28, T31N, R14W	8. FARM OR LEASE NAME Ute Mountain Tribal 1891
14. PERMIT NO.	9. WELL NO. #1
15. ELEVATIONS (Show whether OF, FT, GR, etc.) 5578' GR	10. FIELD AND POOL, OR WILDCAT Verde Gallup
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 28, T31N, R14W
	12. COUNTY OR PARISH San Juan
	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	(Other) <input type="checkbox"/>

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Cement plug 3520' to 3200' with 45 cubic feet slurry.

Perforated 5-1/2" casing at 1300' - failed to part casing but circulated through hole at 1300' created by shot.

Cement plug 1300' to 1200' with 35 cubic feet slurry (100' inside 5-1/2" and 100' in 5-1/2" casing - open hole annulus).

Shot off 5-1/2" casing at 263'.

Cement plug 263' to surface with 90 cubic feet slurry.

Set and cemented dry hole marker. Well permanently plugged and abandoned May 30, 1986. Witnessed by Mr. Jack Kaiser, Petroleum Engineer Technician, Bureau of Land Management, Durango, Colorado.

RECEIVED  
Bureau of Land Management

JUN 17 1986

Durango, Colorado

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Vice President

DATE

6/16/86

(This space for Federal or State office use)

APPROVED BY

L. Mark Hollis

TITLE

ACTING

AREA MANAGER

DATE

SEP 1 1987

CONDITIONS OF APPROVAL, IF ANY:

APPROVED  
AS AMENDED

\*See Instructions on Reverse Side

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any false, fictitious or fraudulent statements or representations as to any matter.

APPROVED TO THE PLUGGING OF THE WELL BORE ONLY. LIABILITY UNDER THE BOND RETAINED UNTIL SURFACE RESTORATION IS COMPLETED AND APPROVED.