



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office San Juan

Lease No. 7122

Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL _____	SUBSEQUENT REPORT OF WATER SHUT-OFF _____
NOTICE OF INTENTION TO CHANGE PLANS _____	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING _____
NOTICE OF INTENTION TO TEST WATER SHUT-OFF _____	SUBSEQUENT REPORT OF ALTERING CASING _____
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL _____	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR _____
NOTICE OF INTENTION TO SHOOT OR ACIDIZE _____	SUBSEQUENT REPORT OF ABANDONMENT _____
NOTICE OF INTENTION TO PULL OR ALTER CASING _____	SUPPLEMENTARY WELL HISTORY _____
NOTICE OF INTENTION TO ABANDON WELL _____	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 1 is located 100 ft. from N line and 100 ft. from E line of sec. 25

Well No. 1 is located 100 ft. from N line and 100 ft. from E line of sec. 25

Well No. 1 is located 100 ft. from N line and 100 ft. from E line of sec. 25

The elevation of the derrick floor above sea level is 522 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Set 152' or 10 5/8 casing with 75 sacks cement -
1 sack calcium chloride.
Plug down 9:30 A.M. 3-12-56
Drilled out 10:00 P.M. - 3-12-56



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company San Juan Mining Co.

Address 1115 Patterson Blvd.

Albuquerque, New Mexico

By [Signature]

Title General Manager

