

(SUBMIT IN TRIPLICATE)

Indian Agency _____

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Ute Mountain Tribal

Allottee _____

Lease No. 14-20-604-84

				X

SUNDRY NOTICES AND REPORTS ON **RECEIVED**

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	X
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 17, 1958

Well No. 2 is located 660 ft. from N line and 540 ft. from E line of sec. 30

NE NE Sec. 30 31N 11W NMPN
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Verde-Gallup San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5580 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

3-14-58 T. D. 430'. Set 10 sacks regular cement in bottom of hole from 430' to 400', filled hole from 30' to 400' with 10' mud & set plug @ 30', filled hole with 10 sacks regular cement from surface to 30'.
Job completed @ 4:30 p.m., 3-14-58



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company THREE STATES NATURAL GAS COMPANY

Address P. O. Box 67
Farmington, New Mexico

By John Coulter
Title Assistant Dist. Supt.

