

|  |  |  |  |  |  |
|--|--|--|--|--|--|
|  |  |  |  |  |  |
|  |  |  |  |  |  |
|  |  |  |  |  |  |
|  |  |  |  |  |  |
|  |  |  |  |  |  |
|  |  |  |  |  |  |

(SUBMIT IN TRIPLICATE)

Indian Agency Ute Indian

UNITED STATES

Contract 14-20-604-124

DEPARTMENT OF THE INTERIOR

Allottee \_\_\_\_\_

GEOLOGICAL SURVEY

Co. Lease No. 234674

## SUNDRY NOTICES AND REPORTS ON WELLS

|  |   |          |
|--|---|----------|
| NOTICE OF INTENTION TO DRILL.....                  | SUBSEQUENT REPORT OF WATER SHUT-OFF.....        | <u>X</u> |
| NOTICE OF INTENTION TO CHANGE PLANS.....           | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING..... |          |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....    | SUBSEQUENT REPORT OF ALTERING CASING.....       |          |
| NOTICE OF INTENTION TO REDRILL OR REPAIR WELL..... | SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....  |          |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....       | SUBSEQUENT REPORT OF ABANDONMENT.....           | <u>X</u> |
| NOTICE OF INTENTION TO PULL OR ALTER CASING.....   | SUPPLEMENTARY WELL HISTORY.....                 |          |
| NOTICE OF INTENTION TO ABANDON WELL.....           |   |          |

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

UTE INDIAN "B"

Farmington, New Mexico October 4, 19 57

Well No. 1 is located 660 ft. from N line and 660 ft. from E line of sec. 25  
1-1

NE/4 Section 25  
(1/4 Sec. and Sec. No.)

T-31-N  
(Twp.)

R-15-W  
(Range)

(Meridian)

Yardley Gallup  
(Field)

San Juan  
(County or Subdivision)

New Mexico  
(State or Territory)

The elevation of the derrick floor above sea level is 5532 ft.

### DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

9/28/57: Spudded at 11:00 P M, 9/27/57.  
9/29/57: Ran 97' - 8-5/8" csg at 111' w/125 sz neat. POB 2:35 PM, 9/28/57. Cmt. circ.  
9/30/57: Tested csg. w/700# for 30 min. OK. Drilled plug at 3:00 PM, 9/29/57.  
10/1/57: Secured USGS app verbal approval to plug crooked hole. Plugged hole from 394' to surface w/140 sz reg cement w/10% sand & 3% Cal. chl. Job complete 6 PM, 9/30/57.

UTE B-1 X

10/2/57: Skidded rig 25' NE of old hole.  
10/3/57: Spudded hole 2:00 AM, 10/2/57.  
10/4/57: Set 99' 8-5/8" csg at 112' w/125 sz neat cement. POB 1:00 PM, 10/3/57. Cement circ.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Humble Oil & Refining Company

Address Box 1268

Farmington, New Mexico

By J. C. Wisoley  
Title Agent



