

NEW MEXICO OIL CONSERVATION COMMISSION
SANTA FE, NEW MEXICO

Form C-110
Revised 7/1/55

(File the original and 4 copies with the appropriate district office)

CERTIFICATE OF COMPLIANCE AND AUTHORIZATION
TO TRANSPORT OIL AND NATURAL GAS

Company or Operator Pan American Petroleum Corporation Lease Ute Mountain Tribal "A"

Well No. 1 Unit Letter D S 28 T 31N R 15W Pool Verde-Gallup

County San Juan Kind of Lease (State, Fed. or Patented) Federal

If well produces oil or condensate, give location of tanks: Unit D S 28 T 31N R 15W

Authorized Transporter of Oil or Condensate El Paso Natural Gas Products Company

Address Box 1565, Farmington, New Mexico
(Give address to which approved copy of this form is to be sent)

Authorized Transporter of Gas _____

Address _____
(Give address to which approved copy of this form is to be sent)


If Gas is not being sold, give reasons and also explain its present disposition:

Reasons for Filing: (Please check proper box) New Well _____ ()

Change in Transporter of (Check One): Oil (☒) Dry Gas () C'head () Condensate ()

Change in Ownership _____ () Other _____ ()

Remarks: _____
(Give explanation below)



The undersigned certifies that the Rules and Regulations of the Oil Conservation Commission have been complied with.

Executed this the 25th day of April 1958

By _____

Approved APR 21 1958 1958

Title Field Clerk

OIL CONSERVATION COMMISSION

Company Pan American Petroleum Corporation

By _____

Address Box 487

Title Supervisor Dist. # 3

Farmington, New Mexico

1		

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency Ute Mountain Tribal
Allottee 14-20-60-69
Lease No. 14-20-60-69

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	<input checked="" type="checkbox"/>		

RECEIVED
SEP 27 1960
U. S. GEOLOGICAL SURVEY
DURANGO, COLO.

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Ute Mountain Tribal "A"

Farmington, New Mexico September 26, 1960

Well No. 1 is located 440 ft. from N line and 970 ft. from E line of sec. 28
SW/4 NW/4 of Section 28 T-31-N R-15-W N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Verde Valley San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 977 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

As a result of Ute Mountain Tribal "A" Well No. 1 ceasing to produce oil in commercial quantities we propose to plug and abandon this well as follows:

1. Spot 25 sacks cement plug on bottom (approximately 200' of fill-up inside casing) and squeeze with minimum pressure to leave perforations covered with cement.
2. Fill hole with fluid.
3. Pump 25 sacks cement down 5-1/2" - 6-5/8" annulus (approximately 140' of fill-up to anchor pipe.)
4. Remove well head and surface equipment.
5. Spot 5 sacks cement for surface plug (0 - 40') and erect dry hole marker.
6. Plug and abandonment by above procedure to permit possible re-entry for future secondary recovery purposes.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Pan American Petroleum Corporation

Address Box 480

Farmington, New Mexico

Attention: L. O. Spoor, Jr.

By

Title

ORIGINAL
R. M.

Area Engineer

