


(SUBMIT IN TRIPLICATE)

Indian Agency Ignacio

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Allottee \_\_\_\_\_

Lease No. 14-00-001-123



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 5, 1959

Well No. 1 is located 500 ft. from N line and 1920 ft. from W line of sec. 23  
23/24, Section 23 T-31N R-12W N. 111. 11.  
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Verde Valley San Juan County New Mexico  
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5505 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Total Depth - 2565'. Run logs: 10' of the Hancock-1300', "A" Marker-1764'. Set 79 joints, 2554', of 1 1/2" casing at 2564' with 65 cu. cement. Top of the cement at 2030.

Set two stage cement collar at 1011 with 65 cu. cement. Top of the cement at 1120.

Moved in cable tool - drilled cement 6/1/59. Tested for 2 hours. 500# pressure - pipe okay.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company AMCO OIL & GAS COMPANY

Address Box 706

Albuquerque, New Mexico

ORIGINAL SIGNED BY JOE C. SALMON

By JOE C. SALMON

Title DISTRICT SUPERINTENDENT