


Form 9-331b
(April 1952) **Sec. 22**

(SUBMIT IN TRIPLICATE)

Indian Agency **Consolidated Ute**



UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee **#14-20-604-83**
Lease No. **Ute Mountain**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

RECEIVED
OCT 29 1959
U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 27, 19**59**

Well No. **9** is located **660** ft. from **N** line and **660** ft. from **E** line of sec. **22**
SW/4 Sec. 22 **31E** **14W** **NMPM**
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Verde Gallup **San Juan** **New Mexico**
 (Field) (County or Subdivision) (State or Territory)

The elevation of the ~~derrick floor~~ **O.L.** above sea level is **5609** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spud 4:30 PM 10-24-59

Set 5 jts. (102') of 8-5/8" csg. at 113' w/80 sax + 2% CaCl₂

Plug down 12:15 PM 10-25-59. Test w/700# 30 min., OK.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Soco Mobil Oil Company, Inc.**

Address **Box 2406**

Hobbs, New Mexico

By *[Signature]*
Title **District Superintendent**

