


*File Copy*

**Ute Mtn. Tribal L/L**

Budget Bureau No. 42-R-359.3.  
Approval expires 12-31-55.

(SUBMIT IN TRIPLICATE)

Indian Agency **Ute Mountain**



**UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY**

Allottee \_\_\_\_\_

Lease No. **11-00-601-1919**

**Sec. 24**

**SUNDRY NOTICES AND REPORTS ON WELLS**

NOTICE OF INTENTION TO DRILL _____	SUBSEQUENT REPORT OF WATER SHUT-OFF _____	
NOTICE OF INTENTION TO CHANGE PLANS _____	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING _____	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF _____	SUBSEQUENT REPORT OF ALTERING CASING _____	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL _____	SUBSEQUENT REPORT OF REDRILLING OR REPAIR _____	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE _____	SUBSEQUENT REPORT OF ABANDONMENT _____	<b>I</b>
NOTICE OF INTENTION TO PULL OR ALTER CASING _____	SUPPLEMENTARY WELL HISTORY _____	
NOTICE OF INTENTION TO ABANDON WELL _____		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

**March 1**, 19**58**

Well No. **191** is located **640** ft. from **N** line and **640** ft. from **E** line of sec. **24**

**SE 1, SE 1, Sec. 24**  
(1/4 Sec. and Sec. No.)

**T1 N 16 W**  
(Twp.) (Range)

**R10W**  
(Meridian)

**Undesignated**  
(Field)

**San Juan County**  
(County or Subdivision)

**New Mexico**  
(State or Territory)

The elevation of the derrick floor above sea level is **5015** ft.

**DETAILS OF WORK**

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

The Ute Mountain Tribal L/L was plugged and abandoned February 14, 1958 by spotting a cement plug (50 sacks) from 1750 feet to 1600 feet through the open hole section. A 20 foot cement plug was placed in the casing at the surface. No casing was pulled from the well and the location has been cleaned and is ready for inspection.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Standard Oil Company of Texas**

Address **Box 1501**  
**Farmington, New Mexico**

By **Charles R. Rantey**

Title **Field Foreman**

