


(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency Durango
Allottee None
Lease No. 24-25-64-20



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)


Well No. 20-2 is located 660 ft. from S line and 660 ft. from E line of sec. 20
15 1/2 Section 20 T-31N R-34W R.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Durango San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5000 ft. 0.1

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

Total depth - 3770'
Sand-oil formed with 1105 lbs. oil and 30,000' sand
Formation pressure - 1000 - 1000'
Fracturing pressure - 1000'
L.S. 47 lbs
Initial shut-in pressure 1000'
Set 50 lbs., 314' of 2 1/2" tubing, landed at 3120'
Run pump and rods to 3120'



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Acme Oil and Gas Company
Address Boxer # 970
Durango, New Mexico
ORIGINAL SIGNED BY JOE C. SALMON
By Joe C. Salmon
Title District Superintendent