


(SUBMIT IN TRIPLICATE)

Indian Agency **Ute Mountain**



UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee _____

Lease No. **Ute Indian Tribal**
Contract No.
14-20-604-123

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL _____	SUBSEQUENT REPORT OF WATER SHUT-OFF _____	XX
NOTICE OF INTENTION TO CHANGE PLANS _____	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING _____	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF _____	SUBSEQUENT REPORT OF ALTERING CASING _____	XX
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL _____	SUBSEQUENT REPORT OF REDRILLING OR REPAIR _____	XX
NOTICE OF INTENTION TO SHOOT OR ACIDIZE _____	SUBSEQUENT REPORT OF ABANDONMENT _____	
NOTICE OF INTENTION TO PULL OR ALTER CASING _____	SUPPLEMENTARY WELL HISTORY _____	1058
NOTICE OF INTENTION TO ABANDON WELL _____		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 27, 19 **58**


Well No. **Ute-Indian 2-3** / is located **660** ft. from **XXXX** line and **2140** ft. from **XXXX** line of sec. **24**
22/24, section 24 (1/4 Sec. and Sec. No.) **T-31-N, R15-W** (Twp.) **R.M.T.M.** (Range) **New Mexico** (Meridian)
Verde-Gallup (Field) **San Juan** (County or Subdivision)

The elevation of the derrick floor above sea level is **5494** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Total Depth 2895. Well completed natural. Open hole 2844 to 2895. Landed 2 3/8" tubing at 2893. Installed rods and pump.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **AZTEC OIL & GAS COMPANY**
Address **P O Box 786**
Farmington, New Mexico

By **ORIGINAL SIGNED BY JOE C. SALMON**
Joe C. Salmon
Title **District Superintendent**