

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency Ute. Mt.

Allottee _____

Lease No. _____

Contract: 14-20-604-86

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	REPORT OF WORKOVER

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

6-17, 19 59

Well No. 3 is located 660 ft. from RD line and 1780 ft. from Flk line of sec. 20


SE 1/4 SW 1/4 of Sec. 20 (1/4 Sec. and Sec. No.) 31N (Twp.) 19W (Range) WPM (Meridian)

Verde Valley (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 5613 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)



Gulf Designatio : SW Barker Dome No. 3

Perforated interval 940'-945' w/4 bullets per ft. Sand-oil fractured 940'-945' w/ 8780 gallons crude oil, 11,250# sand. Reran rods and tubing.

PRIOR TO WORKOVER: Pumped 2 bopd from open hole 1781'-1875'.

AFTER WORKOVER: Pumped 2.6 bopd from open hole 1781'-1875' and perforations 940'-945'.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Gulf Oil Corporation

Address Production Department

P. O. Box 3313

Durango, Colorado

By W. D. Mitchell

Title Area Production Supt.