

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office New Mexico

Lease No. 03157

Unit Sec. 21

Designation Public

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS

U. S. GEOLOGICAL SURVEY

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

APR 10 1952

Well No. 1 is located 220 ft. from S line and 220 ft. from W line of sec. 21

Sec. 21 (4 Sec. and Sec. No.) 31 N (Twp.) 10 W (Range) N.M.P.M. (Meridian)

Blanco (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 5136 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded 4-1-52

Set surface 4-2-52 (286 ft. ground level) of 227 ft. rotary bushings 10 3/4"-40# casing. Baker guide shoe. Pipe set 1 ft. off bottom in 13 3/4" hole. Cemented with 150 sacks common cement. Circulated behind pipe. Tested surface pipe with 500# for 30 minutes. Drilled out shoe and retested with 500# for 30 minutes. Pipe held pressure 0.1. Tested 4-10-52.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company ROCK RIVER OIL & REFINING CO., INC.

Address 321 East Douglas

Richita, Kansas

By A. J. Jackson
Title Dist. Foreman